



DURALUM (Series)

Maintenance of surfaces

Maintenance of painted or anodized surface is important to remain smooth and stain free. To do this, proceed as follow:

- Use clear water and add small doses of neutral or slightly alkaline detergents. Alkaline or excessively acid detergents and active surface agents that may react with aluminum should not be used. Abrasives or abrasive cleaners should not be used. Organic solvents containing ester, alcohol, compound, ether, etc. should not be used. Detergents with unknown components should be avoided. Use only cotton or a soft cloth and apply gentle pressure and not excessive pressure.
- The temperature of the room to be cleaned and detergent should not exceed 77 degrees Fahrenheit / 25 degrees Celsius.
- Never use a steam cleaners.
- Oily, greasy or other substances can be removed with the aid of hydrocarbonated naphtha free of aromatic components.
- Residues of glue, silicone or adhesive tape must be removed immediately and in the same manner.
- After each cleaning, we recommend rinsing immediately with clear, cold water.
- If necessary, the application can be repeated after 24 hours.